BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. :

Date : 23-08-2021

1. Customer's Name and Address with Telephone No. : Sri Maruthi Enterprises
   Pro. Chethan .A

2. Well Location : Doddabommasandra Lake inside near water Purification Plant Centre in ward-10

3. Total Well Depth / Drilled in Ft. : 1180 Ft

4. Casing Erected in Ft. : 260 Ft

5. Water Struck at the Depth of : 1040 Ft

6. Total Yield (Measuring method "V" Norch : 3 inch / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Clear

8. At the Depth of :

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Smitha. NL
AEWIO